

APPENDIX G

SITE AND AREA PHOTOGRAPHS



PHOTOGRAPH LOCATION KEY

**251 Searingtown Rd,
North Hills**

Source: ESRI Web Mapping Service, NYS
Orthophotography, 2013
Scale: 1 inch = 300 feet



DEIS

Manhasset Crest
Site Photographs-March 27th, 2014



1. Fire hydrant located southwest of former retreat house



2. Fireplace inside small 1-story masonry-wood building



3. Landscape or drainage feature looking south from north side of property



4. Looking east down paved site access, fire hydrant, Belgium block curb, water service, stormwater catch basin at end

**Manhasset Crest
Site Photographs-March 27th, 2014**



5. Looking east toward park, invasive species, deciduous forest, moderate & steep slopes



6. Looking north at grouping of weeping trees near center of property



7. Looking northeast from white pine stand toward debris pile and deciduous forest



8. Looking northeast up a moderate & gradual slope toward pool house

**Manhasset Crest
Site Photographs-March 27th, 2014**



9. Looking south from parking lot at former retreat home site



10. Looking south from white pine stand, site of former retreat home on left, debris pile on right



11. Looking south toward multi-family (MF) residential development, chain link fence, woodland in foreground, which provides screening during the spring & summer seasons



12. Looking southeast at storage shed on east side of property, adjacent to east parking lot

**Manhasset Crest
Site Photographs-March 27th, 2014**



13. Looking southwest at former inground pool



14. Looking southwest at pool equipment house



15. Looking southwest at site of former retreat home



16. Looking west across property from south side of former site of retreat home

**Manhasset Crest
Site Photographs-March 27th, 2014**



17. Looking west from parking lot toward demolition debris pile and storage shed



18. Looking east at decorative maze, stairs, large deciduous & evergreen trees



19. Looking west at decorative maze



20. Looking west at multi-family (MF) residences, private road & chainlink fence

**Manhasset Crest
Site Photographs-March 27th, 2014**



21. White pine stand and debris from demolition of building looking south



22. Looking west at reflecting pool on west side of property



23. Searingtown Road looking south from entrance, good sight distance, asphalt sidewalk, new street trees, overhead utilities, sewer in street, traffic signal at park



24. Searingtown Road, looking north, upslope, asphalt sidewalk, two lanes in each direction

**Manhasset Crest
Site Photographs-March 27th, 2014**



25. Site access off Searingtown Road, looking northwest multi-family, residential home in background



26. Site entrance looking east down access road toward Searingtown Road



27. Site of former St. Ignatius retreat home looking west



28. Small stone-wood building sitting/meeting room, fireplace, north side of property looking west

**Manhasset Crest
Site Photographs-March 27th, 2014**



29. Steps and walkway, looking west from west side of site of former retreat home site



30. Stormwater catch basin at access entrance, Belgium block curbing



31. Christopher Morley County Park, looking east at reflecting pond and indoor tennis courts



32. Looking southeast at park entrance, signalized intersection, two lanes in each direction plus, turning lanes